


THB:PP0445701




故障诊断接口 IP02



V4 V6


AMP:1318389-1

接AVM主机 IP60



AMP:368502-1
AMP:174923-1

接胎压监测 IP29
回绑与主千





AMP:2005281-3

接发动机舱-仪表板过渡线



JST:AIT2PB-10-1AK

接EPS IP13





Molex:987861011
接SAS IP32

TYC0:2050723-4

TYC0:2050656-1(1719059-1)

气囊ECU IP45



AMP:1318389-1

接车联网 IP69

					SX6A电气原理图	16.0 诊断通讯					
						图 样 标 记			重 量	比 例	
标 记	处数	更改文件号	签 字	日 期		共 31 张			第 19 张		
设 计			批 准			东风柳州汽车有限公司					
校 对			日 期								
审 核											
工 艺											