







专用工具和设备

图示	工具编号/说明
 72 3007	J 25070 加热枪 500-700 F
 8 17	J 35616 GM端子测试组件
 1306360	J 35616-200 测试灯—插入式诊断装置
 11 18	J 36169-A 带保险丝的跨接线
 11 17	J 38125 端子修理组件
 -572200	J 38125-5 加热枪
 -74	J 39200 数字式万用表
	J 42675

扁平导线探针适配器



5 8. 86



1. 2. 3. 4.

J 43244
继电器拔出钳