

This diagram shows an exploded view of a mechanical assembly. The main component is a large, grey, cast metal housing (1) with a red internal seal or gasket. Below it are several smaller components: a black cylindrical part (2), a black flange or ring (3), a black bracket or support (4), and a grey metal bracket or support (5). Dashed lines indicate the assembly path for each part.

- | | |
|--------------|------------|
| 1. 离合器壳 | 4. 挂档轴承衬套 |
| 2. 挂档轴承1(奇数) | 5. 离合器啮合拨叉 |
| 3. 挂档轴承2(偶数) | |