


[Click here to print](#)

Connector: **C0082L**

CONNECTOR HOUSING NOT SERVICEABLE



Part No.: **YPC800520**

Colour: **BLACK**


Cavities: **8WY**

Harness: **FACIA COMPOSITE HARNESS**

Description: **Clockspring**

Location: **Behind steering column cowl**

Qualifier:



Wire Chart

CAV	CSA	COL	CCT	DESTN
2	0.35D	WS	139L	C0230
3	0.35D	NG	139L	C2238L
4	0.35D	SR	922L	C2819L
4	0.35D	SR	125L	C2515L
5	0.35D	WS	139L	C0581
6	0.35D	BK	139L	S/JOINT SJ663L
7	0.35D	BK	124L	C2819L
7	0.35D	SB	125L	C2515L
8	0.35D	GB	139L	C0582