


[Click here to print](#)

Connector: **C0192L**

CONNECTOR HOUSING NOT SERVICEABLE



Part No.: **YPG800390**

Colour: **TIN PLATED**


Cavities: **1WY**

Harness: **BATTERY POSITIVE PETROL V6 LHD
HARNESS**

Description: **Relay-Transit**

Location: **RH side of engine compartment**

Qualifier: **LHD condition illustrated**



Wire Chart

CAV	CSA	COL	CCT	DESTN
1	50.0D	RD	ALL	C0178L