


[Click here to print](#)

Connector: **C0386**

CONNECTOR HOUSING NOT SERVICEABLE



Part No.: **XUD818960**

Colour: **NO COLOUR**


Cavities: **4WY**

Harness: **TAILGATE UPPER HARNESS**

Description: **Tailgate harness to main harness**

Location: **Rear of headlining - LH side**

Qualifier:



Wire Chart

CAV	CSA	COL	CCT	DESTN
SCR	0.5D	SCR	784	C2788
1	0.13D	BU	784	C2788
2	0.13D	OG	784	C2788
3	0.13D	GN	784	C2788
4	0.13D	BN	784	C2788